


Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA/USDA, USDA/NASA, AeroGRID, IGN, SIA, USFSA, and the USGS Imagery Community



Location 1

Looking North from
road - no clearing of
vegetation necessary



Looking South from
ditch -
Approximately 10 x
10 ft. area that
requires grading of
existing material

Location 2

Looking Southwest
from road -
Approximate 15 x 15
ft. area requires some
pruning of brush and
small shrubs



Looking East from
inside Pond –
Approximately 15 x
10 ft. area requires
some grading of
existing material




Location 3

Looking Southwest
from road -
Approximately 35 x 15
ft. area requires
grading of existing
material



Looking Northeast -
different view of the
area that requires
grading of existing
material



Location 4

Looking North from
roadway -
Approximately 20 x 35
ft. area of shrubs and
small trees that
require pruning and
some clearing



Looking West from
Pond-
Approximately 20 x
40 ft. area of grasses
and small trees that
require pruning and
some clearing

